

### 1.3.3 VIDEO CHECK

First calibrate the machine. To do so, use the following procedure:

- Place a blank A4 sheet of paper in the loading tray of the sheet feeder scanner.
- Enter the key sequence **MENU**, \*, **a**, and validate by pressing **OK**.
- Wait until the machine restarts.

Make some copies with the CIS and check that the quality of the copies is satisfactory.

In the case of a scanner problem, repeat the calibration procedure above.

In the case of a printer problem (the result remains unsatisfactory after scanner calibration):

- Print the logs to check the printer component of the machine.
- Check the consumable.